

XIZI DRIVE DO3000 Error Instruction

	可能的故障原因 Possible Cause	解决措施 Solution
BASE FAULT	变频器有导电物体掉入 Conductive Objects fall into the Inverter	清除杂物 clean up the sundries
	电机三相中的任意两项短路 Two of the Three Phase are in Short Circuit Condition	检查电机电源线 Check the Power Cord
DC link OVT	输入电压过高 Input Voltage too High	检查输入电源电压 Check the input voltage
PVT lost	变频器的编码器回路异常 encoder is having abnormal circuit	查看变频器内编码器电路部分 Check the circuitry of encoder
	编码器连接线断线或短路 Encoder cable is broken or in short circuit condition	检查编码器连接线 Check encoder cable
MOTOR OVERLOAD	开关门过程中受阻 Door open process is impeded	检查是否有异物或机械卡阻 Check about sundries and obstruction of machinery
	门机运行中，电机缺相 Door Motor Meeting Phase-loss when Operating	检查电机电源线 Check Motor Power Cord
POWER LOST	电机三相中任意一相对地短接 One of the phase conductors is short-circuiting	检查电机电源线 Check Motor Power Cable